


Securing the Building Envelope

A diagnostic guide to chimney flashing, leak assessment, and structural preservation for New Zealand properties.




Back Gutter

Channels water safely around the rear blind-spot of the chimney structure.

Pipe Seals

Flexible boots (like Dektite) sealing flue penetrations.




Front Apron

The primary forward-facing shield directing water down the roof profile.

DPC Trays


Internal barriers preventing moisture from wicking down through the masonry.

The Anatomy of a Breach



Mechanical Disruption

Modern wood burners are popular, but post-installation flashing is frequently improperly secured or poorly integrated with aging roof materials.



Thermal Expansion


Metal lengths over 12m require expansion joints. Repeated freeze-thaw cycles without expansion tolerance will tear primary fasteners.



Wind-Driven Ingress

High NZ wind zones demand extreme fastening. Without compressible foam strips or a 3° minimum fall, wind drives moisture uphill.

The Chain Reaction of a Leak




1

Stage 1: The Initial Breach

Corroded metal, cracked mortar, or a failed Dektite seal allows micro-ingress during heavy rain.

Stage 2: The Silent Zone
Moisture pools in the attic space, trapped between walling and insulation. Usually undetectable from ground level.

2



3

Stage 3: Masonry Saturation


Trapped moisture freezes and expands, leading to visible exterior deterioration and efflorescence.

Stage 4: Structural Compromise
Water breaches interior ceilings. Catastrophic repair costs and potential fire hazards from compromised flue ventilation.

4




Clinical Signs of Flashing Failure




Efflorescence

Mineral salts left by evaporating water. A primary indicator of active moisture penetration.




Spalling Bricks

Caused by trapped moisture freezing and expanding. Poses an immediate exterior safety hazard.



Oxidized Components

Rusting indicates the watertight seal between the chimney and the roof has been fundamentally broken.




The Leaning Stack

Critical structural failure. Indicates long-term foundation degradation from unchecked water routing.

The Decision Matrix: Repair vs. Teardown


| | Repair Zone | Replacement Zone |
|-------------------------|---|--|
| Scope of Damage | Limited strictly to mortar, flashing, or the chimney crown. | Deep masonry saturation or flue liner degradation. |
| Structural Stability | Chimney is perfectly vertical and structurally sound. | Noticeable leaning, tilting, or fire damage. |
| Component Failure Count | 1-2 localized component failures. | >2 major components failing |
| Financial Threshold | Estimated costs under \$3,000. | Costs exceed \$4,000–\$6,000 |

Material Selection Protocol



Code 4 Lead

- The traditional heavyweight champion.
- Milled to British Standard BS EN 12588.
- Extremely durable, highly malleable for complex shapes, and 100% recyclable.
- Lifespan measured in decades.



Architectural Aluminium


- The modern alternative, typically 0.9mm (5052 grade).
- Highly recommended when pairing with Duraclad roofing.
- Requires careful engineering to manage thermal expansion on lengths over 12 meters.



Polymer (Dektite/EPDM)

- Engineered specifically for pipe and flue penetrations.
- EPDM handles constant temperatures up to 115°C; Silicone up to 200°C.
- Isolates noise, accommodates roof vibration, and adapts to pitch.

The Financial Dashboard (2026 Projections)



Tier 1: Minor Intervention

Range: \$150 – \$500

Context: Simple, single-visit preventative maintenance.

Includes: Chimney Cap Installation, Minor sealing/patching.

Tier 2: Moderate Restoration

Range: \$500 – \$2,500

Context: Requires specialized sheet metal fabrication or masonry skills.

Includes: Flashing Replacement (\$200–\$800), Crown Repair (\$300–\$1.5k), Repointing.

Tier 3: Major Structural

Range: \$2,500 – \$5,000+

Context: Critical safety restorations requiring scaffolding and engineering.

Includes: Flue Liner Replacement, Complete Rebuilds.

Execution and Risk Management

The Physics of Failure

Professional installation guarantees adherence to strict building geometry:

- ❏ Maintaining a minimum 3° fall to prevent moisture ponding.
- ❏ Providing at least 150mm overlap where roof pitches change.
- ❏ Adjusting fastener frequency specifically for Low (1 per metre) vs. Severe (4 per metre) NZ wind zones.



Flashing operates at the most vulnerable intersection of your property. Improper installation voids warranties, obscures progressive water damage, and masks severe fire hazards like creosote buildup. Securing the envelope requires specialized roofing, plumbing, and masonry expertise—demand a licensed professional.